

Grothe • Kraume

Instruction of Welders in Health and Safety

Work Sheets for the Information
of Welding Personnel

Contents

Transparency

General Topics

1 – 6

Gas Welding and Cutting Processes

7 – 25

Essential hazards ○ Gases used in oxy-fuel processes ○ Storage of acetylene in steel cylinders ○ Acetylene hazards ○ Oxygen hazards ○ Compressed gas cylinders - identification ○ Pressure regulators - requirements - identification - operation ○ Gas hoses - requirements - operation ○ Safety devices - requirements - operation ○ Gas torches - requirements - operation

Arc Welding Processes

26 – 42

Essential hazards ○ Electrical current - Effect on the human body - Protective measures against current flowing through the body ○ Arc welding equipment ○ Welding power sources - requirements - identification ○ Stick electrode holders - requirements ○ Arc welding torches - requirements ○ Wire feed units - requirements ○ Arc welding equipment - operation stick electrode holders, welding current leads ○ Increased hazard of electric shock

Process-related Hazards and Countermeasures

43 – 102

Process-related hazards and countermeasures ○ Optical radiation - general - skin protection - protection of eyes and face - technical protection of welders - technical protection of bystanders ○ noise - protective measures ○ Hazardous substances - definitions - effect - limiting and guide values - measurement methods ○ Characteristics and incidence ○ Defence against hazardous substances - equipment and measures - switching processes - optimisation of working conditions; positioning of the workpiece, gas processes, manual arc welding, metal-inert gas welding, avoidance of phosgene formation, coated workpieces, technical protective equipment, ventilation

Welding under Special Conditions

103 – 120

Welding under special conditions and countermeasures ○ welding in confined spaces - welding in fire hazard areas ○ welding on vessels with hazardous contents

Occupational Health Surveillance

121 – 123