

Contents

Preface	xxi
Introduction.....	xxiii
Acknowledgements.....	xxv

CASTING METALLURGY

CHAPTER 1 The Melt	3
1.1 Reactions of the Melt with its Environment.....	5
1.2 Transport of Gases in Melts	9
1.3 Surface Film Formation.....	11
1.4 Vaporisation	14
CHAPTER 2 Entrainment	17
2.1 Entrainment Defects	21
2.1.1 Bifilms	21
2.1.2 Bubbles	25
2.1.3 Extrinsic Inclusions	30
2.2 Entrainment Processes	37
2.2.1 Surface Turbulence.....	37
2.2.2 Oxide Skins from Melt Charge Materials.....	46
2.2.3 Pouring.....	47
2.2.4 The Oxide Lap Defect I: Surface Flooding.....	50
2.2.5 Oxide Lap Defect II: The Confluence Weld.....	52
2.2.6 The Oxide Flow Tube	56
2.2.7 Microjetting	57
2.2.8 Bubble Trails	58
2.3 Furling and Unfurling.....	67
2.4 Deactivation of Entrained Films.....	77
2.5 Soluble, Transient Films.....	80
2.6 Detrainment.....	81
2.7 Evidence for Bifilms	83
2.8 The Importance of Bifilms	88
2.9 The Four Common Populations of Bifilms	89
CHAPTER 3 Flow	91
3.1 Effect of Surface Films on Filling.....	91
3.1.1 Effective Surface Tension	91
3.1.2 The Rolling Wave.....	92
3.1.3 The Unzipping Wave.....	92

3.2	Maximum Fluidity (The Science of Unrestricted Flow)	95
	Fluidity Definition	96
3.2.1	Mode of Solidification.....	97
3.2.2	Effect of Velocity	110
3.2.3	Effect of Viscosity (Including Effect of Entrained Bifilms)	110
3.2.4	Effect of Solidification Time t_f	112
3.2.5	Effect of Surface Tension.....	121
3.2.6	Effect of an Unstable Substrate	124
3.2.7	Comparison of Fluidity Tests.....	125
3.2.8	Effect of Vibration.....	128
3.3	Extended Fluidity.....	128
3.4	Continuous Fluidity	131
CHAPTER 4	Moulds and Cores	135
4.1	Moulds: Inert or Reactive	135
4.2	Transformation Zones	136
4.3	Evaporation and Condensation Zones	139
4.4	Mould Atmosphere	144
4.4.1	Composition.....	144
4.4.2	Mould Gas Explosions	145
4.5	Mould Surface Reactions.....	147
4.5.1	Pyrolysis	147
4.5.2	Lustrous Carbon Film	148
4.5.3	Sand Reactions	149
4.5.4	Mould Contamination.....	149
4.5.5	Mould Penetration	151
4.6	Metal Surface Reactions.....	155
4.6.1	Oxidation	155
4.6.2	Carbon (Pickup and Loss).....	155
4.6.3	Nitrogen	156
4.6.4	Sulphur.....	157
4.6.5	Phosphorus.....	157
4.6.6	Surface Alloying.....	158
4.6.7	Grain Refinement	158
4.6.8	Miscellaneous	159
4.7	Mould Coatings.....	159
4.7.1	Aggregate Moulds	159
4.7.2	Permanent Moulds and Metal Chills	160
4.7.3	Dry Coatings.....	161

CHAPTER 5	Solidification Structure	163
5.1	Heat Transfer	163
5.1.1	Resistances to Heat Transfer	163
5.1.2	Increased Heat Transfer	178
5.1.3	Convection	193
5.1.4	Remelting	193
5.1.5	Flow Channel Structure	194
5.2	Development of Matrix Structure	197
5.2.1	General	197
5.2.2	Nucleation of the Solid	198
5.2.3	Growth of the Solid	201
5.2.4	Disintegration of the Solid (Grain Multiplication)	209
5.3	Segregation	213
5.3.1	Planar Front Segregation	213
5.3.2	Microsegregation	216
5.3.3	Dendritic Segregation	218
5.3.4	Gravity Segregation	219
CHAPTER 6	Casting Alloys	223
6.1	Zinc Alloys	223
6.2	Magnesium Alloys	227
6.2.1	Films on Liquid Mg Alloys + Protective Atmospheres	228
6.2.2	Strengthening Mg Alloys	230
6.2.3	Microstructure	234
6.2.4	Inclusions	235
6.3	Aluminium	236
6.3.1	Oxide Films on Al Alloys	237
6.3.2	Entrained Inclusions	239
6.3.3	Grain Refinement (Nucleation and Growth of the Solid)	239
6.3.4	Dendrite Arm Spacing (DAS) and Grain Size	244
6.3.5	Modification of Eutectic Si in Al-Si Alloys	244
6.3.6	Iron-Rich Intermetallics	259
6.3.7	Other Intermetallics	262
6.3.8	Thermal Analysis of Al Alloys	264
6.3.9	Hydrogen in Al Alloys	267
6.4	Copper Alloys	269
6.4.1	Surface Films	270
6.4.2	Gases in Copper-Based Alloys	270
6.4.3	Grain Refinement	274

6.5	Cast Iron.....	275
6.5.1	Reactions with Gases	275
6.5.2	Surface Films on Liquid Cast Irons.....	277
6.5.3	Cast Iron Microstructures.....	288
6.5.4	Flake Graphite Iron and Inoculation.....	290
6.5.5	Nucleation and Growth of the Austenite Matrix	299
6.5.6	Coupled Eutectic Growth of Graphite and Austenite.....	300
6.5.7	Spheroidal Graphite Iron (Ductile Iron)	302
6.5.8	Compacted Graphite Iron.....	308
6.5.9	Chunky Graphite	310
6.5.10	White Iron (Iron Carbide).....	312
6.5.11	General.....	313
6.5.12	Summary of Structure Hypothesis	314
6.6	Steels	314
6.6.1	Carbon Steels.....	315
6.6.2	Stainless Steels	316
6.6.3	Inclusions in Carbon and Low-Alloy Steels: General Background	317
6.6.4	Entrained Inclusions	319
6.6.5	Primary Inclusions.....	322
6.6.6	Secondary Inclusions and Second Phases.....	324
6.6.7	Nucleation and Growth of the Solid	326
6.6.8	Structure Development in the Solid.....	329
6.7	Nickel-Base Alloys	330
6.7.1	Air Melting and Casting.....	331
6.7.2	Vacuum Melting and Casting.....	332
6.8	Titanium	335
6.8.1	Ti Alloys.....	336
6.8.2	Melting and Casting Ti Alloys.....	336
6.8.3	Surface Films on Ti Alloys	339
CHAPTER 7	Porosity	341
7.1	Shrinkage Porosity	341
7.1.1	General Shrinkage Behaviour	341
7.1.2	Solidification Shrinkage	342
7.1.3	Feeding Criteria.....	348
7.1.4	Feeding: The Five Mechanisms	352
7.1.5	Initiation of Shrinkage Porosity.....	365
7.1.6	Growth of Shrinkage Pores.....	381
7.1.7	Shrinkage Pore Structure.....	382

7.2	Gas Porosity	387
7.2.1	Entrained Pores (Air Bubbles)	388
7.2.2	Blow Holes	389
7.2.3	Gas Porosity Initiated In Situ.....	398
7.3	Porosity Diagnosis	413
7.3.1	Gas Porosity.....	413
7.3.2	Shrinkage Porosity	414
CHAPTER 8	Cracks and Tears	417
8.1	Hot Tearing	417
8.1.1	General.....	417
8.1.2	Grain Boundary Wetting by the Liquid	420
8.1.3	Pre-Tear Extension	421
8.1.4	Strain Concentration.....	423
8.1.5	Stress Concentration.....	424
8.1.6	Tear Initiation	425
8.1.7	Tear Growth.....	426
8.1.8	Prediction of Hot Tearing Susceptibility	429
8.1.9	Methods of Testing.....	433
8.1.10	Methods of Control	436
8.1.11	Summary of the Conditions for Hot Tearing and Porosity	440
8.1.12	Hot Tearing in Stainless Steels	442
8.1.13	Predictive Techniques.....	442
8.2	Cold Cracking	442
8.2.1	General.....	442
8.2.2	Crack Initiation.....	444
8.2.3	Crack Growth	444
CHAPTER 9	Properties of Castings	447
9.1	Test Bars	447
9.2	The Statistics of Failure.....	450
9.2.1	Background of Using Weibull Analysis	453
9.2.2	Procedure for Two-Parameter Weibull Analysis	455
9.2.3	Three-Parameter Weibull Analysis	459
9.2.4	bi-Weibull Distributions	459
9.2.5	Limits of Accuracy.....	461
9.2.6	Extreme Value Distributions	461
9.3	Effect of Defects.....	463
9.3.1	Inclusion Types.....	464
9.3.2	Gas Porosity.....	465
9.3.3	Shrinkage Porosity	466
9.3.4	Tears, Cracks and Bifilms	467

9.4	Tensile Properties	470
9.4.1	Micro-structural Failure	470
9.4.2	Ductility	473
9.4.3	Yield Strength.....	477
9.4.4	Tensile Strength.....	490
9.5	Fracture Toughness.....	493
9.6	Fatigue.....	498
9.6.1	High Cycle Fatigue	498
9.6.2	Low Cycle, High Strain and Thermal Fatigue	506
9.7	Elastic (Young's) Modulus and Damping Capacity.....	507
9.8	Residual Stress.....	508
9.9	High Temperature Tensile Properties.....	509
9.10	Oxidation and Corrosion Resistance.....	511
9.10.1	Internal Oxidation.....	512
9.10.2	Corrosion	514
9.10.3	Pitting Corrosion	515
9.10.4	Filiform Corrosion.....	517
9.10.5	Inter-granular Corrosion.....	518
9.10.6	Stress Corrosion Cracking.....	519
9.11	Leak-Tightness.....	519
9.12	Surface Finish	523
9.12.1	Effect of Surface Tension.....	523
9.12.2	Effects of a Solid Surface Film.....	525
9.13	Quality Indices.....	526
9.14	Bifilm-Free Properties	527

CASTING MANUFACTURE

Introduction to the Casting Manufacturing Industry	529
--	-----

SECTION 1

CHAPTER 10	The 10 Rules for Good Castings	535
10.1	Rule 1: Use a Good-Quality Melt.....	536
10.1.1	Background.....	536
10.2	Rule 2: Avoid Turbulent Entrainment (The Critical Velocity Requirement).....	542
10.2.1	Introduction	542
10.2.2	Maximum Velocity Requirement	543
10.2.3	The No-Fall Requirement	547
10.3	Rule 3: Avoid Laminar Entrainment of the Surface Film (The Non-Stopping, Non-Reversing Condition)	550
10.3.1	Continuous Expansion of the Meniscus.....	550
10.3.2	Arrest of Forward Motion of the Meniscus.....	551
10.3.3	Waterfall Flow: The Oxide Flow Tube.....	552

10.3.4	Horizontal Stream Flow	553
10.3.5	Hesitation and Reversal.....	555
10.3.6	Oxide Lap Defects.....	556
10.4	Rule 4: Avoid Bubble Damage	557
10.4.1	The Bubble Trail	557
10.4.2	Bubble Damage	557
10.4.3	Bubble Damage in Gravity Filling Systems.....	559
10.4.4	Bubble Damage in Counter-gravity Systems.....	560
10.5	Rule 5: Avoid Core Blows	561
10.5.1	Background.....	561
10.5.2	Outgassing Pressure in Cores.....	564
10.5.3	Core Blow Model Study.....	569
10.5.4	Prevention of Blows	569
10.5.5	Summary of Blow Prevention.....	573
10.6	Rule 6: Avoid Shrinkage Damage.....	573
10.6.1	Definitions and Background.....	573
10.6.2	Feeding to Avoid Shrinkage Problems	574
10.6.3	The Seven Feeding Rules.....	575
10.6.4	The New Feeding Logic.....	596
10.6.5	Freezing Systems Design (Chills, Fins and Pins).....	600
10.6.6	Feeding: The Five Mechanisms	600
10.6.7	Computer Modelling of Feeding.....	601
10.6.8	Random Perturbations to Feeding.....	602
10.6.9	The Non-Feeding Roles of Feeders	602
10.7	Rule 7: Avoid Convection Damage	603
10.7.1	The Academic Background.....	603
10.7.2	The Engineering Imperatives	603
10.7.3	Convection Damage and Casting Section Thickness	608
10.7.4	Countering Convection.....	610
10.8	Rule 8: Reduce Segregation Damage	610
10.9	Rule 9: Reduce Residual Stress	613
10.9.1	Introduction	613
10.9.2	Residual Stress from Casting	613
10.9.3	Residual Stress from Quenching.....	617
10.9.4	Controlled Quenching Using Polymer and Other Quenchants	620
10.9.5	Controlled Quenching Using Air	623
10.9.6	Strength Reduction by Heat Treatment	624
10.9.7	Distortion	626
10.9.8	Heat Treatment Developments.....	626
10.9.9	Beneficial Residual Stress	628
10.9.10	Stress Relief.....	628
10.9.11	Epilogue.....	631

10.10	Rule 10: Provide Location Points	631
10.10.1	Datums	631
10.10.2	Location Points	633
10.10.3	Location Jigs	637
10.10.4	Clamping Points	637
10.10.5	Potential for Integrated Manufacture	638

SECTION 2 FILLING SYSTEM DESIGN

CHAPTER 11	Filling System Design Fundamentals	641
11.1	The Maximum Velocity Requirement	642
11.2	Gravity Pouring: The 'No-Fall' Conflict	642
11.3	Reduction or Elimination of Gravity Problems	646
11.4	Surface Tension Controlled Filling	651
CHAPTER 12	Filling System Components	657
12.1	Pouring Basin	657
12.1.1	The Conical Basin	657
12.1.2	Inert Gas Shroud	660
12.1.3	Contact Pouring	660
12.1.4	The Offset Basin	661
12.1.5	The Offset Step (Weir) Basin	662
12.1.6	The Sharp-Cornered or Undercut Basin	667
12.1.7	Stopper	669
12.2	Sprue (Down-Runner)	669
12.2.1	Multiple Sprues	675
12.2.2	Division of Sprues	677
12.2.3	Sprue Base	678
12.2.4	The Well	679
12.2.5	The Radial Choke	681
12.2.6	The Radius of the Sprue-Runner Junction	681
12.3	Runner	683
12.3.1	The Tapered Runner	687
12.3.2	The Expanding Runner	688
12.4	Gates	690
12.4.1	Siting	690
12.4.2	Direct and Indirect	690
12.4.3	Total Area of Gate(s)	691
12.4.4	Gating Ratio	691
12.4.5	Multiple Gates	692
12.4.6	Premature Filling Problem via Early Gates	692

12.4.7	Horizontal Velocity in the Mould	695
12.4.8	Junction Effect.....	696
12.4.9	The Touch Gate	700
12.4.10	Knife Gate	701
12.4.11	The Pencil Gate	702
12.4.12	The Horn Gate.....	703
12.4.13	Vertical End Gate	703
12.4.14	Direct Gating Into the Mould Cavity.....	706
12.4.15	Flow Channel Structure.....	706
12.4.16	Indirect Gating (Into an Up-Runner/Riser).....	707
12.4.17	Central versus External Systems.....	710
12.4.18	Sequential Gating	711
12.4.19	Priming Techniques	712
12.4.20	Tangential Filter Gate.....	714
12.4.21	Trident Gate.....	715
12.5	Surge Control Systems	716
12.6	Vortex Systems	719
12.6.1	Vortex Sprue	720
12.6.2	Vortex Well	721
12.6.3	Vortex Runner (The Offset Runner)	722
12.6.4	Vortex Gate.....	723
12.7	Inclusion Control: Filters and Traps	724
12.7.1	Dross Trap (or Slag Trap)	724
12.7.2	Slag Pockets	725
12.7.3	Swirl Trap.....	726
12.8	Filters	728
12.8.1	Strainers	729
12.8.2	Woven Cloth or Mesh	729
12.8.3	Ceramic Block Filters	733
12.8.4	Leakage Control	735
12.8.5	Filters in Running Systems	739
12.8.6	Tangential Placement	741
12.8.7	Direct Pour	742
12.8.8	Sundry Aspects.....	744
12.8.9	Summary.....	745
CHAPTER 13	Filling System Design Practice	747
13.1	Background to the Methoding Approach.....	748
13.2	Selection of a Layout	748
13.3	Weight and Volume Estimates	748
13.4	Pressurised Versus Unpressurised	750
13.5	Selection of a Pouring Time	755

13.6	Thin Sections and Slow Filling	758
13.7	Fill Rate	758
13.8	Pouring Basin Design.....	759
13.9	Sprue (Down-Runner) Design.....	759
13.10	Runner Design	763
13.11	Gate Design	765

SECTION 3 PROCESSING (MELTING, MOULDING, CASTING, SOLIDIFYING)

CHAPTER 14	Melting	769
14.1	Batch Melting	769
14.1.1	Liquid Metal Delivery	769
14.1.2	Reverberatory Furnaces.....	770
14.1.3	Crucible Melting (Electric Resistance or Gas Heated)	771
14.1.4	Induction Melting	772
14.1.5	Automatic Bottom Pouring	772
14.2	Continuous Melting	772
14.2.1	Tower (Shaft) Furnaces	772
14.2.2	Dry Hearth Furnaces for Non-Ferrous Metals.....	773
14.3	Holding, Transfer and Distribution	774
14.3.1	Holder Failure Modes.....	776
14.3.2	Transfer and Distribution Systems.....	776
14.4	Melt Treatments.....	777
14.4.1	Degassing.....	777
14.4.2	Detrainment (Cleaning).....	783
14.4.3	Additions	787
14.4.4	Pouring.....	788
14.5	Cast Material.....	790
14.5.1	Liquid Metal	790
14.5.2	Partially Solid Mixtures	791
14.6	Re-Melting Processes	794
14.6.1	Electro-Slag Re-Melting	794
14.6.2	Vacuum Arc Re-Melting	795
CHAPTER 15	Moulding	797
15.1	Inert Moulds and Cores	797
15.1.1	Permanent Metal Moulds (Dies).....	797
15.1.2	Salt Cores	799
15.1.3	Ceramic Moulds and Cores.....	800
15.1.4	Magnetic Moulding	802
15.2	Aggregate Moulding Materials	802
15.2.1	Silica Sand.....	803
15.2.2	Chromite Sand.....	804

15.2.3	Olivine Sand	804
15.2.4	Zircon Sand	805
15.2.5	Other Minerals.....	805
15.2.6	Carbon	806
15.2.7	Synthetic Aggregates.....	806
15.3	Binders	807
15.3.1	Greensand (Clay + Water).....	807
15.3.2	Dry Sand.....	808
15.3.3	Chemical Binders	808
15.3.4	Effset Process (Ice Binder)	812
15.3.5	Loam.....	812
15.3.6	Cement Binders	813
15.3.7	Fluid (Castable) Sand.....	813
15.4	Other Aggregate Mould Processes	813
15.4.1	Precision Core Assembly	813
15.4.2	Machined-to-Form.....	813
15.4.3	Unbonded Aggregate Moulds	814
15.5	Rubber Moulds	814
15.6	Reclamation and Re-Cycling of Aggregates.....	814
15.6.1	Aggregate Reclamation in an Al Foundry	814
15.6.2	Aggregate Reclamation in a Ductile Iron Foundry	816
15.6.3	Aggregate Reclamation with Soluble Inorganic Binders	817
15.6.4	Facing and Backing Sands	818
CHAPTER 16	Casting	821
16.1	Gravity Casting.....	821
16.1.1	Gravity Pouring of Open Moulds	821
16.1.2	Gravity Pouring of Closed Moulds	822
16.1.3	Two-Stage Filling (Priming Techniques).....	825
16.1.4	Vertical Stack Moulding.....	826
16.1.5	Horizontal Stack Moulding (H Process).....	826
16.1.6	Postscript to Gravity Filling.....	827
16.2	Horizontal Transfer Casting	827
16.2.1	Level Pour (Side Pour).....	828
16.2.2	Controlled Tilt Casting.....	829
16.2.3	Roll-over as a Casting Process.....	835
16.2.4	Roll-over After Casting (Sometimes Called Inversion Casting).....	836
16.3	Counter-Gravity	838
16.3.1	Low-Pressure Casting.....	842
16.3.2	Liquid Metal Pumps	846
16.3.3	Direct Vertical Injection.....	853
16.3.4	Programmable Control	855

16.3.5	Feedback Control	855
16.3.6	Failure Modes of Low-Pressure Casting.....	856
16.4	Centrifugal Casting.....	856
16.5	Pressure-Assisted Casting	861
16.5.1	High-Pressure Die Casting	862
16.5.2	Squeeze Casting	868
16.6	Lost Wax and Other Ceramic Mould Casting Processes.....	871
16.7	Lost Foam Casting	875
16.8	Vacuum Moulding (V Process).....	878
16.9	Vacuum-Assisted Casting.....	880
16.10	Vacuum Melting and Casting.....	881
CHAPTER 17	Controlled Solidification Techniques.....	883
17.1	Conventional Shaped Castings	883
17.2	Directional Solidification.....	883
17.3	Single Crystal Solidification.....	885
17.4	Rapid Solidification Casting.....	887
CHAPTER 18	Dimensional Accuracy.....	893
18.1	The Concept of Net Shape	897
18.1.1	Effect of the Casting Process	898
18.1.2	Effect of Expansion and Contraction.....	899
18.1.3	Effect of Cast Alloy	900
18.2	Mould Design	900
18.2.1	General Issues.....	900
18.2.2	Assembly Methods	902
18.3	Mould Accuracy	904
18.3.1	Aggregate Moulds	904
18.3.2	Ceramic Moulds	907
18.3.3	Metal Moulds (Dies)	907
18.4	Tooling Accuracy.....	909
18.5	Casting Accuracy.....	910
18.5.1	Uniform Contraction	910
18.5.2	Nonuniform Contraction (Distortion)	915
18.5.3	Process Comparison	923
18.5.4	General Summary	924
18.6	Metrology.....	924
CHAPTER 19	Post-Casting Processing	927
19.1	Surface Cleaning.....	927
19.2	Heat Treatment	929
19.2.1	Homogenisation and Solution Treatments.....	929
19.2.2	Heat Treatment Reduction and/or Elimination.....	930

19.2.3 Blister Formation.....	932
19.2.4 Incipient Melting.....	933
19.2.5 Fluid Beds.....	934
19.2.6 Quenching.....	935
19.3 Hot Isostatic Pressing	935
19.4 Machining	938
19.5 Painting	940
19.6 Plastic Working (Forging, Rolling, Extrusion)	941
19.7 Impregnation.....	942
19.8 Non-Destructive Testing	942
19.8.1 X-ray Radiography	942
19.8.2 Dye Penetrant Inspection	943
19.8.3 Leak Testing	943
19.8.4 Resonant Frequency Testing	944
Appendix I.....	947
Appendix II	951
Appendix III.....	955
Appendix IV.....	957
References	959
Index.....	993